




National Inspection Services
: 174456 on 10/10/2019
VIN: 1M2AC08C27M013339

Commercial Credit Group, Inc Mark Wenzel
227 w trade st Charlotte, NC 28202 USA
(704) 414-2456

2007 MACK LE613

LE613 Specifications	
Mileage	134,362 / 13,335 ECM
Engine Hours	7590
Engine	Mack E7
Engine Brake	No
Engine Serial	11843097685.2
Fuel	Diesel 1 Steel Tank 80 Gal. Total
Transmission	Allison Auto 3000RDS 6 Spd
Rear	Mack
Axles	Tandem 20,000 Front / 46,000 Rear
GVWR (lbs)	66,000
Frame Type	Steel
Suspension	Spring
Tire Size F	315/80R22.5
Tire Size R	315/80R22.5
Wheels	Steel
Exterior	139"H 96"W 25'L
A/C	Yes * Operational
Interior Color	BLACK
Radio Config	AM/FM/CD * Operational
Power Mirrors	Dual Power
Hi Back Seats	Driver Side Only
Pass Seat	Stationary
Exterior Color	WHITE
Bumper	Painted
Heated Mirrors	No
External Visor	No

Drive Options
Overdrive, Cruise Control, Power Steering



Notes / Description
Truck has a massive air leak would not build pressure could not move. Block in by other vehicles.



National Inspection Services
 # : 174456 on 10/10/2019
 VIN: 1M2AC08C27M013339

Commercial Credit Group, Inc Mark Wenzel
 227 w trade st Charlotte, NC 28202 USA
 (704) 414-2456

2007 MACK LE613 PHOTOS







National Inspection Services
 # : 174456 on 10/10/2019
 VIN: 1M2AC08C27M013339

Commercial Credit Group, Inc Mark Wenzel
 227 w trade st Charlotte, NC 28202 USA
 (704) 414-2456

2007 MACK LE613

Brakes	
Disc	Disc
16	11
22	18
Additional Brake Detail	
front disc	

Tires			
Front 315/80R22.5	11 / 32 Steel	19 / 32 Steel	Rear 315/80R22.5
Toyo 15 / 32 Steel	Bridgestone 15 / 32 Steel	Firestone 15 / 32 Steel	Firestone 11 / 32 Steel
Dunlop 17 / 32 Steel	Toyo 16 / 32 Steel	Toyo 16 / 32 Steel	Dunlop 18 / 32 Steel
Additional Tire Detail			
steers are Sumitomo brand			

General Observations						
Oil Milky? No	Oil Leaks? Yes	Water Leaks? No	Oil in Coolant? No	Clutch Play? NA	Starts? Yes	Drives? See
Notes						
Safety / Operational Observations						
Lights Work? Yes - All	Wipers Work? Yes	Gauges Work? Yes - All	City Horn Works? No	Air Horn Works? Yes		
Additional Observation Detail						
Leak at oil pan. City horn inoperable.						

Wear and Tear Items	
diagnostics	33-5, 766-4, 516-8, 533-2
air lines	massive air leak, would not build pressure could not move truck
ICC bumper	bent and twisted
windshield	cracked
interior	dirty, seats stained
mirrors	power mirrors not working properly
paint	various chips and scratches
fuel tank	dented
bed	varying levels of rust / rust damage

REPORT WAS PREPARED BY A THIRD PARTY. ALL EQUIPMENT PHOTOGRAPHS ON THIS REPORT DEPICT USED EQUIPMENT AND ("SELLER") DOES NOT ASSERT THEIR ACCURACY OR COMPLETENESS. SELLER IS NOT A MANUFACTURER, DEALER OR SERVICER OF EQUIPMENT. PHYSICAL INSPECTION OF THE USED EQUIPMENT DEPICTED HEREIN IS ENCOURAGED, AND ANY PURCHASING DECISIONS SHOULD BE BASED UPON SUCH ACTUAL INSPECTION THEREOF AS THE INTERESTED PERSON DEEMS APPROPRIATE. SELLER MAKES NO REPRESENTATIONS OR WARRANTIES WHATSOEVER. THE PROPERTY IS SOLD "AS IS" AND "WHERE IS", AND SELLER MAKES NO REPRESENTATION OR WARRANTY, EXPRESS OR IMPLIED, WITH RESPECT TO ANY MATTER WHATSOEVER, INCLUDING, WITHOUT LIMITATION, TITLE, THE CONDITION OF THE PROPERTY, ITS MERCHANTABILITY OR ITS FITNESS FOR ANY PARTICULAR PURPOSE. SELLER SPECIFICALLY DISCLAIMS ANY SUCH REPRESENTATIONS AND WARRANTIES. SELLER IS NOT A MANUFACTURER OR DEALER OF THE PROPERTY. THE FOREGOING TERMS AND CONDITIONS OF SALE AND DISCLAIMER CANNOT BE MODIFIED OR TERMINATED ORALLY. ONLY A WRITTEN INSTRUMENT, SIGNED BY AN OFFICER OF SELLER, SHALL BE EFFECTIVE TO MODIFY OR TERMINATE ANY PROVISIONS THERE OF BUT ONLY TO THE EXTENT SPECIFICALLY SET FORTH THEREIN.