



Commercial Credit Group, Inc (Mark Wenzel)
525 N Tryon Street, Charlotte, NC 28202 USA
(704) 414-2456

VIN: 3HSDJAPR8GN278579

2016 INTERNATIONAL PROSTAR

SPECIFICATIONS	
ENGINE	CUMMINS ISX15 450 HP
ENG BRAKE	YES
ENG SERIAL	79865722
FUEL / TANKS	DIESEL - 2 ALUM 200 GAL TOTAL
EXHAUST	HORIZONTAL
TRANSMISSION	EATON FAOM-15810S-EC3 10 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
AXLE TYPE	TANDEM - F 13,200 LB / R 40,000 LB
GVWR	53,200
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	228"
TIRE SIZE	F 295 75R 22.5 / R 295/75R/22.5
WHEELS	F ALUMINUM / R ALUMINUM
WHEEL 5TH	AIR SLIDE
AIR COND	YES
AUX POWER UNIT?	YES
SLEEPER	73"
DUAL BUNK	YES
INTERIOR COLOR	GRAY
RADIO	AM/FM / CD
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	AIR RIDE
EXTERIOR COLOR	WHITE
BUMPER	CHROME
EXTERIOR OPTS	HEATED MIRRORS, FULL FAIRINGS
COLLISION AVOIDANCE?	YES



BRAKES	
LEFT FRONT	RIGHT FRONT
24	24
LEFT REAR 1	RIGHT REAR 1
22	22
LEFT REAR 2	RIGHT REAR 2
21	18

TIRES & WHEELS			
LEFT FRONT		RIGHT FRONT	
12 / 32 GOODYEAR ALUMINUM		11 / 32 GOODYEAR ALUMINUM	
LEFT OUTER 1	LEFT INNER 1	RIGHT INNER 1	RIGHT OUTER 1
25 / 32 COOPER ALUMINUM	25 / 32 COOPER ALUMINUM	24 / 32 COOPER ALUMINUM	25 / 32 COOPER ALUMINUM
LEFT OUTER 2	LEFT INNER 2	RIGHT INNER 2	RIGHT OUTER 2
26 / 32 HANKOOK ALUMINUM	26 / 32 HANKOOK ALUMINUM	25 / 32 COOPER ALUMINUM	25 / 32 COOPER ALUMINUM
FRONT TIRES: 295 75R 22.5		REAR TIRES: 295/75R/22.5	

GENERAL OBSERVATIONS

OIL MILKY?	NO	LIGHTS WORK?	SEE NOTES
OIL LEAKS?	YES	WIPERS WORK?	SEE NOTES
WATER LEAKS?	NO	GAUGES WORK?	SEE NOTES
OIL IN COOLANT ?	NO	AIR HORN WORKS?	SEE NOTES
CLUTCH PLAY?	NA	CITY HORN WORKS?	SEE NOTES
STARTS?	SEE NOTES		
DRIVES	SEE NOTES		

ADDITIONAL OBSERVATIONS


SEE PAGE AT BOTTOM OF BLOCK / OIL PAN.

WEAR & TEAR DETAIL

BATTERIES	WEAK - NOT HOLDING CHARGE, WILL NOT START
PAINT	VARIOUS CHIPS AND SCRATCHES
SEATS	SHOWING SIGNS OF WEAR
APU	MISSING TOP COVER, CABINET BENT - INOPERATIVE
BAGGAGE DOOR	LEFT SIDE WILL NOT LATCH
1/4 FENDERS	MISSING AND/OR REMOVED
FUEL TANK	RIGHT SIDE MISSING CAP
INTERIOR	NEEDS CLEANING AND DETAIL

REPORT PHOTOS







Condition report only. National Inspection Services does not guarantee mechanical reliability.

© National Inspection Services
101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com