



National Inspection Services
 # : 171365 on 07/31/2019
 VIN: 1XPBD48X8FD247272

Commercial Credit Group, Inc Mark Wenzel
 227 w trade st Charlotte, NC 28202 USA
 (704) 414-2456

2015 PETERBILT 579

579 Specifications	
Mileage	434,287 / 434,289 ECM
Engine Hours	10664
Engine	Cummins ISX15 450 HP
Engine Brake	No
Engine Serial	79744712
Fuel	Diesel 2 Alum Tanks 200 Gal. Total
Exhaust	Single
Transmission	Eaton AutoShift FAOM-15810S 10 Spd
Rear	Meritor 2.93
Axles	Tandem 12,000 Front / 34,000 Rear
GVWR (lbs)	46,000
Frame Type	Steel
Suspension	Air Ride
Wheelbase	236"
Tire Size F	11R22.5
Tire Size R	11R22.5
Wheels	Aluminum
5th Wheel	Air Slide
A/C	Yes * See Notes
Aux Power Unit	Yes * Not Operational
Sleeper Size	70"
Dual Bunks	Yes
Interior Color	GREY
Radio Config	AM/FM/CD * See Notes
Power Mirrors	Dual Power
Hi Back Seats	Dual
Pass Seat	Air Ride
Exterior Color	WHITE
Bumper	Chrome
Heated Mirrors	Yes
Fairings	Full
External Visor	Yes

Drive Options
Overdrive, Cruise Control, Power Steering

Inspection Photos



Notes / Description



National Inspection Services
: 171365 on 07/31/2019
VIN: 1XPBD48X8FD247272

Commercial Credit Group, Inc Mark Wenzel
227 w trade st Charlotte, NC 28202 USA
(704) 414-2456

2015 PETERBILT 579 PHOTOS







National Inspection Services
 # : 171365 on 07/31/2019
 VIN: 1XPBD48X8FD247272

Commercial Credit Group, Inc Mark Wenzel
 227 w trade st Charlotte, NC 28202 USA
 (704) 414-2456

2015 PETERBILT 579

Brakes	
Covered	Covered
Covered	Covered
Covered	Covered
Additional Brake Detail	
Covered	

Tires			
Front 11R22.5	12 / 32 Aluminum	15 / 32 Aluminum	Rear 11R22.5
11 / 32 Aluminum	Cooper 20 / 32 Steel	12 / 32 Steel	12 / 32 Aluminum
10 / 32 Aluminum	10 / 32 Steel	11 / 32 Steel	15 / 32 Aluminum
Additional Tire Detail			
Both front tires are sailun. Left rear one outer is a good ride. Left rear to both our Arisun. Right outer front Airsun inside DynaTrac. Right rear two DynaTrac and Advance.			

General Observations													
Oil Milky?	See Notes	Oil Leaks?	Yes	Water Leaks?	No	Oil in Coolant?	No	Clutch Play?	NA	Starts?	No	Drives?	No
Safety / Operational Observations													
Lights Work?	See Notes	Wipers Work?	See Notes	Gauges Work?	See Notes	City Horn Works?	See Notes	Air Horn Works?	See Notes				
Additional Observation Detail													
Unit towed in, will not start. Could not perform operational checklist. Transmission is leaking.													

Wear and Tear Items	
Refrigerator	Handle does not work
Mud flaps	Missing
1/4 fender	Left side missing
Daignostics	ABS 627-4, engine 3251-0 (aftertreatment fault)
Paint	Various chips and scratches

REPORT WAS PREPARED BY A THIRD PARTY. ALL EQUIPMENT PHOTOGRAPHS ON THIS REPORT DEPICT USED EQUIPMENT AND ("SELLER") DOES NOT ASSERT THEIR ACCURACY OR COMPLETENESS. SELLER IS NOT A MANUFACTURER, DEALER OR SERVICER OF EQUIPMENT. PHYSICAL INSPECTION OF THE USED EQUIPMENT DEPICTED HEREIN IS ENCOURAGED, AND ANY PURCHASING DECISIONS SHOULD BE BASED UPON SUCH ACTUAL INSPECTION THEREOF AS THE INTERESTED PERSON DEEMS APPROPRIATE. SELLER MAKES NO REPRESENTATIONS OR WARRANTIES WHATSOEVER. THE PROPERTY IS SOLD "AS IS" AND "WHERE IS", AND SELLER MAKES NO REPRESENTATION OR WARRANTY, EXPRESS OR IMPLIED, WITH RESPECT TO ANY MATTER WHATSOEVER, INCLUDING, WITHOUT LIMITATION, TITLE, THE CONDITION OF THE PROPERTY, ITS MERCHANTABILITY OR ITS FITNESS FOR ANY PARTICULAR PURPOSE. SELLER SPECIFICALLY DISCLAIMS ANY SUCH REPRESENTATIONS AND WARRANTIES. SELLER IS NOT A MANUFACTURER OR DEALER OF THE PROPERTY. THE FOREGOING TERMS AND CONDITIONS OF SALE AND DISCLAIMER CANNOT BE MODIFIED OR TERMINATED ORALLY. ONLY A WRITTEN INSTRUMENT, SIGNED BY AN OFFICER OF SELLER, SHALL BE EFFECTIVE TO MODIFY OR TERMINATE ANY PROVISIONS THERE OF BUT ONLY TO THE EXTENT SPECIFICALLY SET FORTH THEREIN.