



National Inspection Services  
# : 171368 on 08/05/2019  
VIN: 3HSDJAPR3GN222792 Unit: 1119

Commercial Credit Group, Inc Mark Wenzel  
227 w trade st Charlotte, NC 28202 USA  
(704) 414-2456

## 2016 INTERNATIONAL PROSTAR

PROSTAR Specifications	
Engine	Cummins ISX 425 HP
Engine Brake	Yes
Fuel	Diesel 2 Alum Tanks 200 Gal. Total
Exhaust	Horizontal
Transmission	Eaton Manual 10 Spd
Rear	Meritor
Axles	Tandem 12,000 Front / 40,000 Rear
GVWR (lbs)	52,000
Frame Type	Steel
Suspension	Air Ride
Wheelbase	226"
Tire Size F	11R22.5
Tire Size R	11R22.5
Wheels	Steel
5th Wheel	Air Slide
A/C	Yes * See Notes
Sleeper Size	73"
Dual Bunks	Yes
Interior Color	WHITE
Radio Config	AM/FM/CD * See Notes
Power Mirrors	Dual Power
Hi Back Seats	Dual
Pass Seat	Air Ride
Exterior Color	WHITE
Bumper	Plastic
Heated Mirrors	Yes
Fairings	Full
External Visor	Yes

Drive Options
Overdrive, Cruise Control, Power Steering

### Inspection Photos



Notes / Description





National Inspection Services  
# : 171368 on 08/05/2019  
VIN: 3HSDJAPR3GN222792 Unit: 1119

Commercial Credit Group, Inc Mark Wenzel  
227 w trade st Charlotte, NC 28202 USA  
(704) 414-2456

## 2016 INTERNATIONAL PROSTAR PHOTOS







National Inspection Services  
 # : 171368 on 08/05/2019  
 VIN: 3HSDJAPR3GN222792 Unit: 1119

Commercial Credit Group, Inc Mark Wenzel  
 227 w trade st Charlotte, NC 28202 USA  
 (704) 414-2456

## 2016 INTERNATIONAL PROSTAR

Brakes	
19	17
18	17
18	18
Additional Brake Detail	

Tires			
Front 11R22.5	Falken 9 / 32 Steel	Falken 10 / 32 Steel	Rear 11R22.5
Bridgestone 7 / 32 Steel	Bridgestone 8 / 32 Steel	4 / 32 Steel	4 / 32 Steel
Bridgestone 4 / 32 Steel	Bridgestone 3 / 32 Steel	Continental 2 / 32 Steel	10 / 32 Steel
Additional Tire Detail			
Ironman Tires on the rear			

General Observations	
Oil Milky? No	Oil Leaks? No
Water Leaks? No	Oil in Coolant? No
Clutch Play? NA	Starts? No
Drives? No	
Safety / Operational Observations	
Lights Work? See Notes	Wipers Work? See Notes
Gauges Work? See Notes	City Horn Works? Yes
Air Horn Works? See Notes	
Additional Observation Detail	
City Horn worked but the dash would not come on even when you hook up the jump box. Unit would not start, could not perform operational checklist.	

Wear and Tear Items	
Visor	Cracked
Front Bumper	Scratched and small rock screen damaged
Small Dents	Small dents on the corner of the cab rear.
Tires	8 below terms
Cab extenders	Damaged bboth sides
Rear of cab	Cracked / damaged
1/4 fenders	Damaged
Mud flaps	Missing
Paint	Various chips and scratches
Interior	Soiled

Condition report only. National Inspection Services does not guarantee mechanical reliability.

REPORT WAS PREPARED BY A THIRD PARTY. ALL EQUIPMENT PHOTOGRAPHS ON THIS REPORT DEPICT USED EQUIPMENT AND ("SELLER") DOES NOT ASSERT THEIR ACCURACY OR COMPLETENESS. SELLER IS NOT A MANUFACTURER, DEALER OR SERVICER OF EQUIPMENT. PHYSICAL INSPECTION OF THE USED EQUIPMENT DEPICTED HEREIN IS ENCOURAGED, AND ANY PURCHASING DECISIONS SHOULD BE BASED UPON SUCH ACTUAL INSPECTION THEREOF AS THE INTERESTED PERSON DEEMS APPROPRIATE. SELLER MAKES NO REPRESENTATIONS OR WARRANTIES WHATSOEVER. THE PROPERTY IS SOLD "AS IS" AND "WHERE IS", AND SELLER MAKES NO REPRESENTATION OR WARRANTY, EXPRESS OR IMPLIED, WITH RESPECT TO ANY MATTER WHATSOEVER, INCLUDING, WITHOUT LIMITATION, TITLE, THE CONDITION OF THE PROPERTY, ITS MERCHANTABILITY OR ITS FITNESS FOR ANY PARTICULAR PURPOSE. SELLER SPECIFICALLY DISCLAIMS ANY SUCH REPRESENTATIONS AND WARRANTIES. SELLER IS NOT A MANUFACTURER OR DEALER OF THE PROPERTY. THE FOREGOING TERMS AND CONDITIONS OF SALE AND DISCLAIMER CANNOT BE MODIFIED OR TERMINATED ORALLY. ONLY A WRITTEN INSTRUMENT, SIGNED BY AN OFFICER OF SELLER, SHALL BE EFFECTIVE TO MODIFY OR TERMINATE ANY PROVISIONS THERE OF BUT ONLY TO THE EXTENT SPECIFICALLY SET FORTH THEREIN.