



National Inspection Services  
# : 174457 on 11/01/2019  
VIN: 1HTGSSHT8DJ125396

Commercial Credit Group, Inc Mark Wenzel  
227 w trade st Charlotte, NC 28202 USA  
(704) 414-2456

## 2013 INTERNATIONAL 7600

7600 Specifications	
Engine	International Maxxforce DT466 7.6L
Engine Brake	No
Fuel	Diesel 1 Alum Tank 50 Gal. Total
Transmission	Allison Auto 3000 HS 6 Spd
Rear	Spicer
Axles	Tri 20,000 Front / 46,000 Rear
GVWR (lbs)	66,000
Frame Type	Steel
Suspension	Walking Beam
Wheelbase	278"
Tire Size F	425/65R22.5
Tire Size R	315/80R22.5
Wheels	Steel
Exterior	135"H 102"W 26"L
A/C	Yes * See Notes
Interior Color	GRAY / BLACK
Radio Config	AM/FM * See Notes
Hi Back Seats	Dual
Pass Seat	Air Ride
Exterior Color	WHITE
Bumper	Painted
Heated Mirrors	No
External Visor	No

Drive Options
Cruise Control, Power Steering

### Inspection Photos



Notes / Description



National Inspection Services  
# : 174457 on 11/01/2019  
VIN: 1HTGSSHT8DJ125396

Commercial Credit Group, Inc Mark Wenzel  
227 w trade st Charlotte, NC 28202 USA  
(704) 414-2456

## 2013 INTERNATIONAL 7600 PHOTOS







National Inspection Services  
 # : 174457 on 11/01/2019  
 VIN: 1HTGSSHT8DJ125396

Commercial Credit Group, Inc Mark Wenzel  
 227 w trade st Charlotte, NC 28202 USA  
 (704) 414-2456

## 2013 INTERNATIONAL 7600

Brakes	
24	covered
15	14
13	16
13	18
Additional Brake Detail	

Tires			
Front 4.25/65R22.5	6 / 32 Steel	5 / 32 Steel	Rear 3.15/80R22.5
13 / 32 Steel			18 / 32 Steel
Goodyear 16 / 32 Steel			Michelin 15 / 32 Steel
BFGoodrich 16 / 32 Steel		0 Steel	14 / 32 Steel
Additional Tire Detail			
steers, tags, RRO, RRI are Sumitomo brand			

General Observations													
Oil Milky?	No	Oil Leaks?	Yes	Water Leaks?	No	Oil in Coolant?	No	Clutch Play?	NA	Starts?	No	Drives?	No
Safety / Operational Observations													
Lights Work?	See Notes	Wipers Work?	See Notes	Gauges Work?	See Notes	City Horn Works?	See Notes	Air Horn Works?	See Notes				
Additional Observation Detail													
Unit will not start. Leak at oil pan, front cover and both sides of block.													

Wear and Tear Items	
tires	left steer, LFO, RRI, RRO tires are flat, missing inner tires
interior	dirty, seats torn
fenders	scraped
bumper	dented, bent
cab	dents
steps	dented, bent, peeling, rusty
paint	chips at doors, fenders, bumper, hood, skirts, fairings, cab, frame, axles, packer box
packer	water inside, rear steps bent
mirror	left side mount damaged
rust	

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© 2019 National Inspection Services (NIS)  
101 W. Shrader St. Liberty, MO 64068  
[www.nationalinspect.com](http://www.nationalinspect.com)

**REPORT WAS PREPARED BY A THIRD PARTY. ALL EQUIPMENT PHOTOGRAPHS ON THIS REPORT DEPICT USED EQUIPMENT AND ("SELLER") DOES NOT ASSERT THEIR ACCURACY OR COMPLETENESS. SELLER IS NOT A MANUFACTURER, DEALER OR SERVICER OF EQUIPMENT. PHYSICAL INSPECTION OF THE USED EQUIPMENT DEPICTED HEREIN IS ENCOURAGED, AND ANY PURCHASING DECISIONS SHOULD BE BASED UPON SUCH ACTUAL INSPECTION THEREOF AS THE INTERESTED PERSON DEEMS APPROPRIATE. SELLER MAKES NO REPRESENTATIONS OR WARRANTIES WHATSOEVER. THE PROPERTY IS SOLD "AS IS" AND "WHERE IS", AND SELLER MAKES NO REPRESENTATION OR WARRANTY, EXPRESS OR IMPLIED, WITH RESPECT TO ANY MATTER WHATSOEVER, INCLUDING, WITHOUT LIMITATION, TITLE, THE CONDITION OF THE PROPERTY, ITS MERCHANTABILITY OR ITS FITNESS FOR ANY PARTICULAR PURPOSE. SELLER SPECIFICALLY DISCLAIMS ANY SUCH REPRESENTATIONS AND WARRANTIES. SELLER IS NOT A MANUFACTURER OR DEALER OF THE PROPERTY. THE FOREGOING TERMS AND CONDITIONS OF SALE AND DISCLAIMER CANNOT BE MODIFIED OR TERMINATED ORALLY. ONLY A WRITTEN INSTRUMENT, SIGNED BY AN OFFICER OF SELLER, SHALL BE EFFECTIVE TO MODIFY OR TERMINATE ANY PROVISIONS THERE OF BUT ONLY TO THE EXTENT SPECIFICALLY SET FORTH THEREIN.**