



National Inspection Services  
 # : 178078 on 12/26/2019  
 VIN: 4V4NC9EH0GN965992

Commercial Credit Group, Inc Mark Wenzel  
 227 w trade st Charlotte, NC 28202 USA  
 (704) 414-2456

## 2016 VOLVO VNL670

VNL670 Specifications	
Engine	Volvo D13 455 HP
Engine Brake	Yes
Engine Serial	1126760
Fuel	Diesel 2 Alum Tanks 250 Gal. Total
Exhaust	Vertical
Transmission	Volvo Auto ATO2612D 10 Spd
Rear	Meritor 3.08
Axles	Tandem 13,200 Front / 40,000 Rear
GVWR (lbs)	53,200
Frame Type	Steel
Suspension	Air Ride
Tire Size F	295/75R22.5
Tire Size R	295/75R22.5
Wheels	Aluminum
5th Wheel	Air Slide
A/C	Yes * See Notes
Sleeper Size	61"
Dual Bunks	Yes
Interior Color	GRAY
Radio Config	AM/FM/CD * See Notes
Power Mirrors	Dual Power
Hi Back Seats	Dual
Pass Seat	Air Ride
Exterior Color	WHITE
Bumper	Painted
Heated Mirrors	Yes
Fairings	Full
External Visor	Yes

Drive Options
Overdrive, Cruise Control, Power Steering

### Inspection Photos



Notes / Description



National Inspection Services  
# : 178078 on 12/26/2019  
VIN: 4V4NC9EH0GN965992

Commercial Credit Group, Inc Mark Wenzel  
227 w trade st Charlotte, NC 28202 USA  
(704) 414-2456

## 2016 VOLVO VNL670 PHOTOS







National Inspection Services  
 # : 178078 on 12/26/2019  
 VIN: 4V4NC9EH0GN965992

Commercial Credit Group, Inc Mark Wenzel  
 227 w trade st Charlotte, NC 28202 USA  
 (704) 414-2456

## 2016 VOLVO VNL670

Brakes	
20	20
20	24
20	22
Additional Brake Detail	

Tires			
Front 295/75R22.5	Firestone 12 / 32 Aluminum	Firestone 13 / 32 Aluminum	Rear 295/75R22.5
18 / 32 Aluminum	17 / 32 Aluminum	17 / 32 Aluminum	19 / 32 Aluminum
19 / 32 Aluminum	18 / 32 Aluminum	16 / 32 Aluminum	18 / 32 Aluminum
Additional Tire Detail			
Drive Tires HappyRoad Brand			

General Observations						
Oil Milky? No	Oil Leaks? Yes	Water Leaks? No	Oil in Coolant? No	Clutch Play? NA	Starts? No	Drives? No
Safety / Operational Observations						
Lights Work? See Notes	Wipers Work? See Notes	Gauges Work? See Notes	City Horn Works? See Notes	Air Horn Works? See Notes		
Additional Observation Detail						
Vehicle would not start. Shop had dash torn apart. Engine goes into protect mode as soon as started and vehicle shuts down per the shop. Could not perform operational checklist. Leak left side of oil pan.						

Wear and Tear Items	
Hood	Section Missing on Passenger Side
Bumper	Scrapped, Chipped, Bent and Cracked
Dash	Dash and Gauges Removed and sitting in cab - shop working on issue
Passenger Door	Key Lock is Missing and Door Does Not Open
Fairing	Cracked right side
Rear Of Cab	Air Dam Damaged Right side
Mud flaps	Right Hanger Damaged
Paint	Various chips and scratches

REPORT WAS PREPARED BY A THIRD PARTY. ALL EQUIPMENT PHOTOGRAPHS ON THIS REPORT DEPICT USED EQUIPMENT AND ("SELLER") DOES NOT ASSERT THEIR ACCURACY OR COMPLETENESS. SELLER IS NOT A MANUFACTURER, DEALER OR SERVICER OF EQUIPMENT. PHYSICAL INSPECTION OF THE USED EQUIPMENT DEPICTED HEREIN IS ENCOURAGED, AND ANY PURCHASING DECISIONS SHOULD BE BASED UPON SUCH ACTUAL INSPECTION THEREOF AS THE INTERESTED PERSON DEEMS APPROPRIATE. SELLER MAKES NO REPRESENTATIONS OR WARRANTIES WHATSOEVER. THE PROPERTY IS SOLD "AS IS" AND "WHERE IS", AND SELLER MAKES NO REPRESENTATION OR WARRANTY, EXPRESS OR IMPLIED, WITH RESPECT TO ANY MATTER WHATSOEVER, INCLUDING, WITHOUT LIMITATION, TITLE, THE CONDITION OF THE PROPERTY, ITS MERCHANTABILITY OR ITS FITNESS FOR ANY PARTICULAR PURPOSE. SELLER SPECIFICALLY DISCLAIMS ANY SUCH REPRESENTATIONS AND WARRANTIES. SELLER IS NOT A MANUFACTURER OR DEALER OF THE PROPERTY. THE FOREGOING TERMS AND CONDITIONS OF SALE AND DISCLAIMER CANNOT BE MODIFIED OR TERMINATED ORALLY. ONLY A WRITTEN INSTRUMENT, SIGNED BY AN OFFICER OF SELLER, SHALL BE EFFECTIVE TO MODIFY OR TERMINATE ANY PROVISIONS THERE OF BUT ONLY TO THE EXTENT SPECIFICALLY SET FORTH THEREIN.