



National Inspection Services
 # : 174467 on 10/07/2019
 VIN: 3HSCXAPRXHN570570 Unit: 1096

Commercial Credit Group, Inc Mark Wenzel
 227 w trade st Charlotte, NC 28202 USA
 (704) 414-2456

2017 INTERNATIONAL LONESTAR

LONESTAR Specifications	
Mileage	328,286
Engine Hours	8140
Engine	Cummins ISX 450 HP
Engine Brake	Yes
Engine Serial	79938403
Fuel	Diesel 2 Alum Tanks 300 Gal. Total
Exhaust	Dual Chrome
Ext. Breathers	Dual
Transmission	Eaton Manual RTLO-16913A 13 Spd
Rear	Meritor
Axles	Tandem 13,200 Front / 40,000 Rear
GVWR (lbs)	53,200
Frame Type	Steel
Suspension	Air Ride
Wheelbase	250"
Tire Size F	295/75/R22.5
Tire Size R	295/75/R22.5
Wheels	Aluminum
5th Wheel	Air Slide
A/C	Yes * See Notes
Sleeper Size	70"
Dual Bunks	Yes
Interior Color	GREY
Radio Config	AM/FM/CD * Operational
Power Mirrors	Dual Power
Hi Back Seats	Dual
Pass Seat	Air Ride
Exterior Color	GREEN
Bumper	Chrome
Heated Mirrors	Yes
Fairings	Cab / Roof
External Visor	Yes

Drive Options
Overdrive, Cruise Control, Power Steering

Inspection Photos



Notes / Description



National Inspection Services
: 174467 on 10/07/2019
VIN: 3HSCXAPRXHN570570 Unit: 1096

Commercial Credit Group, Inc Mark Wenzel
227 w trade st Charlotte, NC 28202 USA
(704) 414-2456

2017 INTERNATIONAL LONESTAR PHOTOS







National Inspection Services
 # : 174467 on 10/07/2019
 VIN: 3HSCXAPRXHN570570 Unit: 1096

Commercial Credit Group, Inc Mark Wenzel
 227 w trade st Charlotte, NC 28202 USA
 (704) 414-2456

2017 INTERNATIONAL LONESTAR

Brakes	
23	23
23	23
23	23
Additional Brake Detail	

Tires			
Front 295/75/R22.5	Goodyear 8 / 32 Aluminum	Goodyear 10 / 32 Aluminum	Rear 295/75/R22.5
Goodyear 11 / 32 Aluminum	Goodyear 16 / 32 Aluminum	Goodyear 14 / 32 Aluminum	Goodyear 14 / 32 Aluminum
Hankook 10 / 32 Aluminum	Hankook 13 / 32 Aluminum	Goodyear 17 / 32 Aluminum	Goodyear 8 / 32 Aluminum
Additional Tire Detail			
RECAPS ON UNIT			

General Observations	
Oil Milky? No	Oil Leaks? No
Water Leaks? No	Oil in Coolant? No
Clutch Play? Ok	Starts? No
Drives? See Notes	
Safety / Operational Observations	
Lights Work? Yes - All	Wipers Work? Yes
Gauges Work? See Notes	City Horn Works? Yes
Air Horn Works? See Notes	
Additional Observation Detail	
UNIT WILL NOT START DUE TO LOW VOLTAGE. NO POWER AT DATA LINK J1939.	

Wear and Tear Items	
INTERIOR	DATA PLUG FELL DOWN BEHIND KICK PANEL WHEN UNHOOKING DATA READER
DASH	SCRATCHED
BUMPER	DAMAGED
HOOD	PAINT PEELING
MUD FLAP HANGERS	RUSTED
INTERIOR	SOILED
SEATS	RIGHT AND LEFT SEATS STAINED AND WORN, RIGHT SIDE DAMAGED ARM REST MISSING
WINDSHIELD	CHIPPED
MIRROR	LEFT SIDE SCRATCHED
TIRES	2 BELOW TERMS
PAINT	VARIOUS CHIPS AND SCRATCHES

Condition report only. National Inspection Services does not guarantee mechanical reliability.

© 2019 National Inspection Services (NIS)
101 W. Shrader St. Liberty, MO 64068
www.nationalinspect.com

REPORT WAS PREPARED BY A THIRD PARTY. ALL EQUIPMENT PHOTOGRAPHS ON THIS REPORT DEPICT USED EQUIPMENT AND ("SELLER") DOES NOT ASSERT THEIR ACCURACY OR COMPLETENESS. SELLER IS NOT A MANUFACTURER, DEALER OR SERVICER OF EQUIPMENT. PHYSICAL INSPECTION OF THE USED EQUIPMENT DEPICTED HEREIN IS ENCOURAGED, AND ANY PURCHASING DECISIONS SHOULD BE BASED UPON SUCH ACTUAL INSPECTION THEREOF AS THE INTERESTED PERSON DEEMS APPROPRIATE. SELLER MAKES NO REPRESENTATIONS OR WARRANTIES WHATSOEVER. THE PROPERTY IS SOLD "AS IS" AND "WHERE IS", AND SELLER MAKES NO REPRESENTATION OR WARRANTY, EXPRESS OR IMPLIED, WITH RESPECT TO ANY MATTER WHATSOEVER, INCLUDING, WITHOUT LIMITATION, TITLE, THE CONDITION OF THE PROPERTY, ITS MERCHANTABILITY OR ITS FITNESS FOR ANY PARTICULAR PURPOSE. SELLER SPECIFICALLY DISCLAIMS ANY SUCH REPRESENTATIONS AND WARRANTIES. SELLER IS NOT A MANUFACTURER OR DEALER OF THE PROPERTY. THE FOREGOING TERMS AND CONDITIONS OF SALE AND DISCLAIMER CANNOT BE MODIFIED OR TERMINATED ORALLY. ONLY A WRITTEN INSTRUMENT, SIGNED BY AN OFFICER OF SELLER, SHALL BE EFFECTIVE TO MODIFY OR TERMINATE ANY PROVISIONS THERE OF BUT ONLY TO THE EXTENT SPECIFICALLY SET FORTH THEREIN.