



National Inspection Services
 # : 189938 on 10/01/2020
 VIN: 1XKYD49X9GJ478182 Unit: 6114

Commercial Credit Group, Inc Mark Wenzel
 227 w trade st Charlotte, NC 28202 USA
 (704) 414-2456

2016 KENWORTH T680

T680 Specifications	
Mileage	401,783 / 401,784 ECM
Engine Hours	12570
Engine	Cummins ISX15 14.9L 450 HP
Engine Brake	Yes
Engine Serial	79808470
Fuel	Diesel 2 Alum Tanks 100 Gal. Total
Exhaust	Single
Transmission	Eaton Auto FAOM-15810S=EC2 10 Spd
Rear	Spicer 2.79
Axles	Tandem 12,350 Front / 40,000 Rear
GVWR (lbs)	52,350
Frame Type	Steel
Suspension	Air Ride
Wheelbase	226"
Tire Size F	295/75R22.5
Tire Size R	295/75R22.5
Wheels	Aluminum
5th Wheel	Air Slide
A/C	Yes * See Notes
Sleeper Size	76"
Dual Bunks	Yes
Interior Color	GRAY
Radio Config	AM/FM/CD * Operational
Power Mirrors	Dual Power
Hi Back Seats	Dual
Exterior Color	SILVER
Bumper	Painted
Heated Mirrors	Yes
Fairings	Full
External Visor	No

Drive Options
Overdrive, Cruise Control, Power Steering

Inspection Photos



Notes / Description



National Inspection Services
 # : 189938 on 10/01/2020
 VIN: 1XKYD49X9GJ478182 Unit: 6114

Commercial Credit Group, Inc Mark Wenzel
 227 w trade st Charlotte, NC 28202 USA
 (704) 414-2456

2016 KENWORTH T680 PHOTOS







National Inspection Services
 # : 189938 on 10/01/2020
 VIN: 1XKYD49X9GJ478182 Unit: 6114

Commercial Credit Group, Inc Mark Wenzel
 227 w trade st Charlotte, NC 28202 USA
 (704) 414-2456

2016 KENWORTH T680

Brakes	
19	18
20	19
23	23
Additional Brake Detail	

Tires			
Front 295/75R22.5	Goodyear 10 / 32 Aluminum	Goodyear 8 / 32 Aluminum	Rear 295/75R22.5
Bridgestone 15 / 32 Aluminum	25 / 32 Aluminum	Bridgestone 13 / 32 Aluminum	Bridgestone 13 / 32 Aluminum
Michelin 11 / 32 Aluminum	Michelin 15 / 32 Aluminum	20 / 32 Aluminum	Bridgestone 13 / 32 Aluminum
Additional Tire Detail			
Tires have wear. Rear tires are AEOLUS brand.			

General Observations	
Oil Milky? No	Oil Leaks? Yes
Water Leaks? No	Oil in Coolant? No
Clutch Play? NA	Starts? Yes
Drives? Yes	
Safety / Operational Observations	
Lights Work? Yes - All	Wipers Work? Yes
Gauges Work? Yes - All	City Horn Works? Yes
Air Horn Works? Yes	
Diesel Particulate Filter (DPF): PASS	
Additional Observation Detail	
Seepage at bottom of block / oil pan.	

Wear and Tear Items	
Diagnostics	Check engine lamp is on, 5 Active / 1 Inactive fault detected (see photos for detailed ECM report)
Cab extenders	Lower right cab fairing is damaged
Hood	Damage noted below headlight
Tank Fairings	Scratches noted at right rear fairing
Step Fairings	Left lower step is cracked
Dash	Adhesive residue noted, holes drilled in the dash
Steering Wheel	Worn
Door Locks	Right side door lock pull is missing
Door Panels	Left side door panel pull handle is scratched
Tires	1 measures below 10/32

REPORT WAS PREPARED BY A THIRD PARTY. ALL EQUIPMENT PHOTOGRAPHS ON THIS REPORT DEPICT USED EQUIPMENT AND ("SELLER") DOES NOT ASSERT THEIR ACCURACY OR COMPLETENESS. SELLER IS NOT A MANUFACTURER, DEALER OR SERVICER OF EQUIPMENT. PHYSICAL INSPECTION OF THE USED EQUIPMENT DEPICTED HEREIN IS ENCOURAGED, AND ANY PURCHASING DECISIONS SHOULD BE BASED UPON SUCH ACTUAL INSPECTION THEREOF AS THE INTERESTED PERSON DEEMS APPROPRIATE. SELLER MAKES NO REPRESENTATIONS OR WARRANTIES WHATSOEVER. THE PROPERTY IS SOLD "AS IS" AND "WHERE IS", AND SELLER MAKES NO REPRESENTATION OR WARRANTY, EXPRESS OR IMPLIED, WITH RESPECT TO ANY MATTER WHATSOEVER, INCLUDING, WITHOUT LIMITATION, TITLE, THE CONDITION OF THE PROPERTY, ITS MERCHANTABILITY OR ITS FITNESS FOR ANY PARTICULAR PURPOSE. SELLER SPECIFICALLY DISCLAIMS ANY SUCH REPRESENTATIONS AND WARRANTIES. SELLER IS NOT A MANUFACTURER OR DEALER OF THE PROPERTY. THE FOREGOING TERMS AND CONDITIONS OF SALE AND DISCLAIMER CANNOT BE MODIFIED OR TERMINATED ORALLY. ONLY A WRITTEN INSTRUMENT, SIGNED BY AN OFFICER OF SELLER, SHALL BE EFFECTIVE TO MODIFY OR TERMINATE ANY PROVISIONS THERE OF BUT ONLY TO THE EXTENT SPECIFICALLY SET FORTH THEREIN.