



National Inspection Services
: 189755 on 09/28/2020
VIN: 3AKJGLD58FSGC8625 Unit: 6533

Commercial Credit Group, Inc Mark Wenzel
227 w trade st Charlotte, NC 28202 USA
(704) 414-2456

2015 FREIGHTLINER CASCADIA

CASCADIA Specifications	
Engine	Detroit DD15 14.8L 455 HP
Engine Brake	Yes
Engine Serial	472906S0277382
Fuel	Diesel 2 Alum Tanks 200 Gal. Total
Exhaust	Single
Transmission	Detroit Auto DT12-DA-1650 HD 12 Spd
Rear	Detroit 2.53
Axles	Tandem 12,000 Front / 40,000 Rear
GVWR (lbs)	52,000
Frame Type	Single
Suspension	Air Ride
Wheelbase	230"
Tire Size F	11R22.5
Tire Size R	295/75R22.5
Wheels	Aluminum
5th Wheel	Air Slide
A/C	Yes * See Notes
Sleeper Size	72"
Dual Bunks	No
Interior Color	GRAY
Radio Config	AM/FM/CD * See Notes
Hi Back Seats	Dual
Pass Seat	Air Ride
Exterior Color	BLACK
Bumper	Chrome
Fairings	Full
External Visor	No

Drive Options
Cruise Control, Power Steering

Inspection Photos



Notes / Description



National Inspection Services
: 189755 on 09/28/2020
VIN: 3AKJGLD58FSGC8625 Unit: 6533

Commercial Credit Group, Inc Mark Wenzel
227 w trade st Charlotte, NC 28202 USA
(704) 414-2456

2015 FREIGHTLINER CASCADIA PHOTOS







National Inspection Services
 # : 189755 on 09/28/2020
 VIN: 3AKJGLD58FSGC8625 Unit: 6533

Commercial Credit Group, Inc Mark Wenzel
 227 w trade st Charlotte, NC 28202 USA
 (704) 414-2456

2015 FREIGHTLINER CASCADIA

Brakes	
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
Additional Brake Detail	
Disc Brakes	

Tires			
Front 11R22.5	Bridgestone 7 / 32 Aluminum	Bridgestone 9 / 32 Aluminum	Rear 295/75R22.5
Kelly 5 / 32 Aluminum	Kelly 3 / 32 Aluminum	5 / 32 Steel	4 / 32 Steel
9 / 32 Aluminum	4 / 32 Aluminum	Continental 6 / 32 Steel	Continental 7 / 32 Steel
Additional Tire Detail			
Vehicle equipped with Leao Tire brand on Left rear axle. Danaite brand on right front axle.			

General Observations							
Oil Milky?	No	Oil Leaks?	No	Water Leaks?	No	Oil in Coolant?	No
Clutch Play?	NA	Starts?	No	Drives?	No		
Safety / Operational Observations							
Lights Work?	See Notes	Wipers Work?	See Notes	Gauges Work?	See Notes	City Horn Works?	See Notes
		Air Horn Works?		See Notes			
Additional Observation Detail							
Batteries are dead, no jump start available. Leak at bottom of block / oil pan. Residue noted right side of block under turbo.							

Wear and Tear Items	
Tank Fairings	Left side cracked
Body Fillers	Right side cab to fairing body filler panel is missing
Bumper	Filler panels damaged / missing, bumper bent / dented
Under Bunk Storage	Left side door does not close
Cabinets	Various cabinet doors would not open, trim laying on mattress
Cab extender	Left rear rubber torn
Paint	Various chips and scratches

Condition report only. National Inspection Services does not guarantee mechanical reliability.

REPORT WAS PREPARED BY A THIRD PARTY. ALL EQUIPMENT PHOTOGRAPHS ON THIS REPORT DEPICT USED EQUIPMENT AND ("SELLER") DOES NOT ASSERT THEIR ACCURACY OR COMPLETENESS. SELLER IS NOT A MANUFACTURER, DEALER OR SERVICER OF EQUIPMENT. PHYSICAL INSPECTION OF THE USED EQUIPMENT DEPICTED HEREIN IS ENCOURAGED, AND ANY PURCHASING DECISIONS SHOULD BE BASED UPON SUCH ACTUAL INSPECTION THEREOF AS THE INTERESTED PERSON DEEMS APPROPRIATE. SELLER MAKES NO REPRESENTATIONS OR WARRANTIES WHATSOEVER. THE PROPERTY IS SOLD "AS IS" AND "WHERE IS", AND SELLER MAKES NO REPRESENTATION OR WARRANTY, EXPRESS OR IMPLIED, WITH RESPECT TO ANY MATTER WHATSOEVER, INCLUDING, WITHOUT LIMITATION, TITLE, THE CONDITION OF THE PROPERTY, ITS MERCHANTABILITY OR ITS FITNESS FOR ANY PARTICULAR PURPOSE. SELLER SPECIFICALLY DISCLAIMS ANY SUCH REPRESENTATIONS AND WARRANTIES. SELLER IS NOT A MANUFACTURER OR DEALER OF THE PROPERTY. THE FOREGOING TERMS AND CONDITIONS OF SALE AND DISCLAIMER CANNOT BE MODIFIED OR TERMINATED ORALLY. ONLY A WRITTEN INSTRUMENT, SIGNED BY AN OFFICER OF SELLER, SHALL BE EFFECTIVE TO MODIFY OR TERMINATE ANY PROVISIONS THERE OF BUT ONLY TO THE EXTENT SPECIFICALLY SET FORTH THEREIN.