



**Commercial Credit Group, Inc (Mark Wenzel)**  
525 N Tryon Street, Charlotte, NC 28202 USA  
(704) 414-2456

VIN: 5PVNJ8JV3J4S66862  
PO #: 15090

**2018 HINO 268**

SPECIFICATIONS	
ENGINE	HINO JO8E-WU 7.6L 230 HP
FUEL / TANKS	DIESEL - 1 ALUM 90 GAL TOTAL
TRANSMISSION	ALLISON 2200 RDS 6 SPD AUTO
DRIVE OPTS	POWER STEERING, OVERDRIVE, CRUISE
REAR END	MERITOR 5.57
AXLE TYPE	SINGLE - F 10,000 LB / R 19,000 LB
GVWR	25,950
FRAME	STEEL
SUSPENSION	AIR RIDE
WHEELBASE	175"
TIRE SIZE	11R22.5
WHEELS	F STEEL / R STEEL
REAR D TYPE	ROLL-UP
R DOOR (IN X IN)	91X95
LIFT GATE MAKE	WALTCO
LIFT GATE MODEL	WDV45G2
LIFT GATE CAPAC (LBS)	4500
EXTERIOR W (IN)	102
EXTERIOR L (FT)	26.0
AIR COND	YES
INTERIOR COLOR	GRAY
RADIO	AM/FM / CD
MIRRORS	DUAL POWER
HIGH BACK SEATS	DUAL
PASSENGER SEAT	STATIONARY
EXTERIOR COLOR	WHITE
BUMPER	PAINTED
EXTERIOR OPTS	HEATED MIRRORS



NOTES / DESCRIPTION
DEAD BATTERIES, UNABLE TO START AND TEST.

BRAKES	
<b>LEFT FRONT</b>	<b>RIGHT FRONT</b>
COVERED	COVERED
<b>LEFT REAR 1</b>	<b>RIGHT REAR 1</b>
COVERED	COVERED
ADDITIONAL BRAKE DETAIL	
COVERED NO MEASUREMENTS.	

TIRES & WHEELS			
<b>LEFT FRONT</b>		<b>RIGHT FRONT</b>	
9 / 32 CONTINENTAL STEEL		11 / 32 CONTINENTAL STEEL	
<b>LEFT OUTER 1</b>	<b>LEFT INNER 1</b>	<b>RIGHT INNER 1</b>	<b>RIGHT OUTER 1</b>
13 / 32 CONTINENTAL STEEL	15 / 32 CONTINENTAL STEEL	9 / 32 CONTINENTAL STEEL	9 / 32 CONTINENTAL STEEL
<b>FRONT TIRES: 11R22.5</b>		<b>REAR TIRES: 11R22.5</b>	

**GENERAL OBSERVATIONS**

<b>OIL MILKY?</b>	NO	<b>LIGHTS WORK?</b>	SEE NOTES
<b>OIL LEAKS?</b>	YES	<b>WIPERS WORK?</b>	SEE NOTES
<b>WATER LEAKS?</b>	NO	<b>GAUGES WORK?</b>	SEE NOTES
<b>OIL IN COOLANT ?</b>	NO	<b>AIR HORN WORKS ?</b>	NA
<b>CLUTCH PLAY?</b>	NA	<b>CITY HORN WORKS?</b>	SEE NOTES
<b>STARTS ?</b>	SEE NOTES		
<b>DRIVES</b>	SEE NOTES		

ADDITIONAL OBSERVATIONS
DEAD BATTERIES, UNABLE TO START AND TEST.

WEAR & TEAR DETAIL

ENGINE	NO START, NO ONE ON IMPOUND LOT TO TRY AND JUMPSTART. THIS WAS REPORTED TO THE CUSTOMER.
BOX	RIGHT SIDE SCRAPES & SCRATHES.
BATTERY COVER	MISSING.
MIRRORS	HOOD MIRROR IS BENT
STEERING WHEEL	SURFACE IS WORN.

REPORT PHOTOS





