



National Inspection Services  
# : 191172 on 10/30/2020  
VIN: 1UYVS2534CU458024 Unit: 6504

Commercial Credit Group, Inc Mark Wenzel  
525 N. Tryon Street Charlotte, NC 28202 USA  
(704) 414-2456

## 2012 UTILITY REEFER

REEFER Specifications	
Axles	Tandem 20,000 Front / 20,000 Rear
Spread Axle	No
Suspension	Air Ride
Tire Size F	295/75R22.5
Tire Size R	295/75R22.5
Wheels	Steel
Reefer Type	Diesel
Reefer Make	Carrier
Reefer Model	2500 A
Reefer Hours	31,453
Rear Door	Swing
Side Door	Swing
Exterior	162"H 102"W 53'L
Exterior Color	WHITE

Drive Options

### Inspection Photos



Notes / Description



National Inspection Services  
# : 191172 on 10/30/2020  
VIN: 1UYVS2534CU458024 Unit: 6504

Commercial Credit Group, Inc Mark Wenzel  
525 N. Tryon Street Charlotte, NC 28202 USA  
(704) 414-2456

## 2012 UTILITY REEFER PHOTOS





National Inspection Services  
 # : 191172 on 10/30/2020  
 VIN: 1UYVS2534CU458024 Unit: 6504

Commercial Credit Group, Inc Mark Wenzel  
 525 N. Tryon Street Charlotte, NC 28202 USA  
 (704) 414-2456

## 2012 UTILITY REEFER

Brakes	
19	19
22	20
Additional Brake Detail	

Tires			
Front 295/75R22.5	/ 32	/ 32	Rear 295/75R22.5
Bridgestone 4 / 32 Steel	Bridgestone 4 / 32 Steel	Bridgestone 5 / 32 Steel	Bridgestone 5 / 32 Steel
Bridgestone 4 / 32 Steel	Bridgestone 4 / 32 Steel	Bridgestone 4 / 32 Steel	Bridgestone 4 / 32 Steel
Additional Tire Detail			

General Observations					
Oil Milky? No	Oil Leaks? No	Water Leaks? No	Oil in Coolant? No	Clutch Play? Needs Attention	Starts? Yes Drives? No
Safety / Operational Observations					
Lights Work? NA	Wipers Work? NA	Gauges Work? Yes - All	City Horn Works? NA	Air Horn Works? NA	
Additional Observation Detail					

Wear and Tear Items	
PAINT	CHIPS AND SCRATCHES
PANELS	HOLE NOTED IN RIGHT FRONT CORNER
ICC BUMPER	BENT
REAR DOORS	MINOR DENTS ON RIGHT DOOR
INTERIOR	SCUFFS / SCRATCHES AT WALL LINERS
TIRES	WORN, ALL 8 MEASURE BELOW 10/32

Condition report only. National Inspection Services does not guarantee mechanical reliability.

**REPORT WAS PREPARED BY A THIRD PARTY. ALL EQUIPMENT PHOTOGRAPHS ON THIS REPORT DEPICT USED EQUIPMENT AND ("SELLER") DOES NOT ASSERT THEIR ACCURACY OR COMPLETENESS. SELLER IS NOT A MANUFACTURER, DEALER OR SERVICER OF EQUIPMENT. PHYSICAL INSPECTION OF THE USED EQUIPMENT DEPICTED HEREIN IS ENCOURAGED, AND ANY PURCHASING DECISIONS SHOULD BE BASED UPON SUCH ACTUAL INSPECTION THEREOF AS THE INTERESTED PERSON DEEMS APPROPRIATE. SELLER MAKES NO REPRESENTATIONS OR WARRANTIES WHATSOEVER. THE PROPERTY IS SOLD "AS IS" AND "WHERE IS", AND SELLER MAKES NO REPRESENTATION OR WARRANTY, EXPRESS OR IMPLIED, WITH RESPECT TO ANY MATTER WHATSOEVER, INCLUDING, WITHOUT LIMITATION, TITLE, THE CONDITION OF THE PROPERTY, ITS MERCHANTABILITY OR ITS FITNESS FOR ANY PARTICULAR PURPOSE. SELLER SPECIFICALLY DISCLAIMS ANY SUCH REPRESENTATIONS AND WARRANTIES. SELLER IS NOT A MANUFACTURER OR DEALER OF THE PROPERTY. THE FOREGOING TERMS AND CONDITIONS OF SALE AND DISCLAIMER CANNOT BE MODIFIED OR TERMINATED ORALLY. ONLY A WRITTEN INSTRUMENT, SIGNED BY AN OFFICER OF SELLER, SHALL BE EFFECTIVE TO MODIFY OR TERMINATE ANY PROVISIONS THERE OF BUT ONLY TO THE EXTENT SPECIFICALLY SET FORTH THEREIN.**